SANFL CHANGEROOM FACILITY INCLUSIONS





INCLUSIONS/ADDITIONAL FEATURES	BASHEER	MCINTOSH	LINDSAY	KERLEY	NALEY	GOWANS	ROBRAN	BAGSHAW	BLIGHT	CUNNINGHAM	CORNES	EBERT	REGIONAL SOCIAL COMPLEX
SIZE	42.4 x 24.6 - 879.5m ² TOTAL	42.7 x 10.2 - 412m²TOTAL	39.3 x 10.2 - 377.5m ² TOTAL	35.6 x 10.2 - 329.5m ² TOTAL	28.2 x 10.2 - 277m² TOTAL	25.6 x 8.4 - 212.1m ² TOTAL	22.2 x 8.4 - 184.46m ² TOTAL	19.3 x 12.4 - 240.5m ² TOTAL	19.3 x 12.4 - 240.5m ² TOTAL	19.3 x 12.4 - 240.5m²TOTAL	19.3 x 16.8 - 211.2m ² TOTAL	18.8 x 8.4 - 156.8m ² TOTAL	34 x 15.5 - 505.5m² TOTAL
CHANGEROOM/S	✓	✓	~	~	~	~	~	~	✓	~	~	~	
GYMNASIUM/MULTI-USE ROOM	✓	~											
UMPIRE ROOM/S	~	~	~	~		~	~	~	~	~	~		
DOCTOR ROOM/S	✓	~	~					~	~		~		
MASSAGE ROOM/S	~	~	~					~	~	~	~		
AMENITIES	~	~	~	~	~	~	~	~	~	~	~	~	~
DISABLED AMENITIES	✓							~					✓
STORE/UTILITY ROOM/S	•	~	~	~		~							✓
TIMEKEEPERS BOX	✓												~
KITCHEN	~												✓
SOCIAL AREA WITH BAR	~												✓
FLEXIBILITY OF SOUND RATED OPERABLE OR FIXED WALLS	~	~	~	~	~	~	~	•	✓	~	~	✓	~
PERIMETER CHASSIS DESIGN AND CLOSER FLOOR JOISTS FOR FIRM FLOOR FEEL	~	~	✓	~	~	~	~	~	~	~	~	~	✓
3.0M TALL CEILING HEIGHT THROUGHOUT	~	~	~	~	~	~	~	~	✓	~	~	~	✓
MODERN AND DYNAMIC CUSTOMISED BUILDING FINISHES IN CLUB COLOURS	~	~	~	~	~	~	~	~	~	~	~	~	✓
INTERNAL CEILING AND WALL PROTECTION AND RECESSED LIGHTS TO AVOID DAMAGE FROM BALL IMPACT	•	~	•	~	~	~	•	~	•	~	~	•	~
ENERGY EFFICIENT SENSOR LIGHTING	~	~	~	~	~	~	~	~	~	~	~	~	~
VENTILATION (FANS)	~	~	~	~	~	~	~	~	✓	~	~	~	✓

NOTES:				